

# General Environmental Incident Summary

**Incident:** 5207      **Date/Time Notice:** 8/23/2016      12:00      **DEM Incident No:**

**Responsible Party:** MBI Energy Services

**Date Incident:** 8/22/2016      **Time Incident:** 15:30      **Duration:**

**County:** Billings      **Twp:** 144      **Rng:** 101      **Sec:** 19      **Qtr:**

**Lat:** 47.27094      **Long:** -103.53210      **Method:** Interpolation from map

**Location Description:** Elkhorn Federal 19-1

**Submitted By:** Chad Miller

**Affiliation:**

**Address:** 12890 12th St SW

**City:** Belfield

**State:** ND

**Zip:**

**Received By:**

**Contact Person:**

12890 12th St SW

Belfield , ND

**Distance Nearest Occupied Building:**

**Release Contained:** Yes

**Type of Incident:** Pipeline Leak

**Description of Released Contaminant:** Crude Oil

**Volume Spilled:** 2.00 barrels

**Ag Related:** No

**EPA Extremely Hazardous Substance:** No

**Reported to NRC:** Unknown

**Cause of Incident:**

Truck drove over pressurized pipe, that had been purged and pressurized with 50 psi Nitrogen. The pipe stem broke off at the surface and pressure in pipe pushed some of the contents in the pipe out.

**Risk Evaluation:**

None

**# of Fatalities:**

**# of Injuries:**

**Affected Medium:** 03 - soil

**Potential Environmental Impacts:**

Impacts to soil and nearby vegetation. Once area is washed and cleaned risks are minimal.

**Action Taken or Planned:**

Location is being cleaned up by hydrovac and skid steer. Contaminated material will be disposed of in approved and permitted landfill.

**Wastes Disposal Location:** Permitted Landfill

**Agencies Involved:** US Forest Service

## **Updates**

---

**Date:** 8/23/2016    **Status:** Reviewed - Follow-up Required

**Author:** Schiermeister, Robin

**Updated Volume:**

**Notes:**

Two barrels were found to have gone off site. Further follow-up is needed.

---

**Date:** 8/29/2016    **Status:** Inspection

**Author:** Crowdus, Kory

**Updated Volume:**

**Notes:**

On location 8/29/2016, at 4:20 p.m. Release impacted area off location to the north of location. 40 X 70 yards of vegetation have been cut. I spoke with company contact at location who said Micro-Blaze has been applied to area at request of U.S. Forest Service. There were no impacts to water. Oversight will go to the Forest Service which will monitor remainder of cleanup activities.